



Technical Information

N C S ULTRACURE AC 2

NDS0911/623

MEDIUM CONCENTRATION COBALT ACCELERATOR FOR POLYESTER RESINS

DESCRIPTION

NCS Ultracure AC 2 has been specially formulated for use in polyester resins and gelcoats to achieve shorter gel times with MEKP catlysts.

BENEFITS	FEATURES
For ease of dispersion	Specially designed with suitable solvent.
Small dosages can be easil measured.	Low cobalt level

TYPICAL LIQUID PROPERTIES

PROPERTY	SPECIFICATION	NCS TEST METHOD
Liquid Appearance	Purple Liquid	2
Cobalt Metal content, % (typical)	1	7A
Stability, months	6 minimum	4.1

APPLICATION

The recommended dosage based on polyester resins and gelcoats is up to 2,0 phr*. It should be noted that NCS ULTRACURE AC 2 should be stirred into the polyester resin or gelcoat prior to the addition of catalyst.

*phr - parts per hundred resin, by mass

The information herein is to assist customers in determining whether our products are suitable for their applications. Our products are intended for sale to industrial and commercial customers. We request that customers inspect and test our products before use and satisfy themselves as to contents and suitability. Nothing herein shall constitute any other warranty expressed or implied, including any warranty of merchantability or fitness, nor is protection from any law or patent to be inferred. All patent rights are reserved. The exclusive remedy for all proven claims is replacement of our materials, and in no event shall we be liable for special, incidental, or consequential damages. Ou standard conditions of contract will apply to all sales

STORAGE AND HANDLING To ensure maximum stability and maintain optimum properties, polyester resin should be stored in closed containers, maintained below 25°C and away from heat sources and sunlight. All storage should conform to local fire and building codes. Drum stock should be kept to a reasonable minimum with first-in, first-out stock rotation.

Where bung-in-head containers are stored outside, it is recommended that these be stored in a horizontal position to avoid the ingress of water.

STANDARD PACKAGE

Non-returnable metal drums.

Bulk supplies can be delivered by road tanker.

MATERIAL SAFETY DATA SHEET

A Material Safety Data Sheet is available from your NCS Resins' representative. Make certain that you obtain a copy of this guide to the safe handling of unsaturated polyester resins and resin systems.

PLEASE READ AND UNDERSTAND THE MATERIAL SAFETY DATA SHEET BEFORE WORKING WITH THIS PRODUCT

WARNING: CARE MUST BE TAKEN TO AVOID DIRECT MIXING OF ANY ORGANIC PEROXIDE (CATALYST) WITH METAL SOAPS, AMINE OR ANY OTHER POLYMERISATION ACCELERATOR OR PROMOTER, AS VIOLENT DECOMPOSITION WILL RESULT!

NCS RESINS BRANCHES AT:

JOHANNESBURG / DURBAN / CAPE TOWN / PORT ELIZABETH